


## Main Inspections Pipe Run and Scoring

Project name:	Mainline ID:	City:	Street:
	<b>1</b>	<b>Ashland, MA</b>	<b>Union Street</b>
Start date/time:	Direction:	Weather:	Location code:
<b>2/13/2026 12:53 PM</b>	<b>D</b>	<b>1</b>	
Shape:	Material:	Height:	Width:
<b>C</b>	<b>PVC</b>	<b>12 in.</b>	

### Scores

Calculated at: **2/13/2026 12:56:34 PM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
<b>1</b>	<b>0</b>	<b>0</b>	<b>0000</b>	<b>0.0</b>	<b>0</b>	<b>0</b>	<b>0000</b>	<b>0.0</b>	<b>0</b>	<b>0.0</b>
<b>2</b>	<b>0</b>									
<b>3</b>	<b>0</b>									
<b>4</b>	<b>0</b>									
<b>5</b>	<b>0</b>									




# Main Inspections Pipe Run and Scoring

Project name:	Mainline ID:	City:	Street:
	<b>2</b>	<b>Ashland, MA</b>	<b>Voyager Lane</b>
Start date/time:	Direction:	Weather:	Location code:
<b>2/13/2026 1:55 PM</b>	<b>U</b>	<b>1</b>	
Shape:	Material:	Height:	Width:
<b>C</b>	<b>PVC</b>	<b>12 in.</b>	

## Scores

Calculated at: **2/13/2026 2:02:51 PM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
<b>1</b>	<b>0</b>	<b>0</b>	<b>0000</b>	<b>0.0</b>	<b>0</b>	<b>0</b>	<b>0000</b>	<b>0.0</b>	<b>0</b>	<b>0.0</b>
<b>2</b>	<b>0</b>				<b>0</b>					
<b>3</b>	<b>0</b>				<b>0</b>					
<b>4</b>	<b>0</b>				<b>0</b>					
<b>5</b>	<b>0</b>				<b>0</b>					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
**3** **Ashland, MA** **Voyager Lane Easement**  
 Start date/time: Direction: Weather: Location code:  
**3/4/2026 9:33 AM** **D** **1**  
 Shape: Material: Height: Width:  
**C** **PVC** **12 in.**

## Scores

Calculated at: **3/4/2026 9:41:31 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 10:21 AM U 1  
 Shape: Material: Height: Width:  
 C PVC 12 in.

## Scores

Calculated at: 3/4/2026 10:30:59 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	5	5100	5.0	5	5.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 5 Ashland, MA Presidents Row  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 10:46 AM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/4/2026 10:56:25 AM

Grade	Structural:			O&M:			Overall:			
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0				0					
3	0				0					
4	0				4					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 6 Ashland, MA Presidents Row  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 11:21 AM U 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/4/2026 11:32:31 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0				0					
3	0				0					
4	0				4					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 7 Ashland, MA Presidents Row  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 11:40 AM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/4/2026 11:42:14 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: 3/4/2026 12:03:36 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 3/4/2026 12:20 PM Direction: Weather: Location code:  
 Shape: Material: Height: Width:  
**C PVC 18 in.**

## Scores

Calculated at: 3/4/2026 12:24:56 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 12:33 PM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/4/2026 12:47:38 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	3	3100	3.0	0	0	0000	0.0	3	3.0
2	0									
3	3									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 3/4/2026 12:48 PM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/4/2026 1:00:13 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: 3/4/2026 1:44 PM Direction: U Weather: 1 Location code:  
 Shape: C Material: PVC Height: 18 in. Width:

## Scores

Calculated at: 3/4/2026 1:49:12 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 3/4/2026 1:50 PM Direction: Weather: Location code:  
 Shape: Material: Height: Width:  
**C** **SP** **18 in.**

## Scores

Calculated at: 3/4/2026 1:54:34 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: 3/4/2026 2:08:26 PM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: 3/4/2026 2:30 PM Direction: D Weather: 1 Location code:  
 Shape: C Material: PVC Height: 18 in. Width:

## Scores

Calculated at: 3/5/2026 8:11:32 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name:	Mainline ID:	City:	Street:
	<b>16</b>	<b>Ashland, MA</b>	<b>Main Street</b>
Start date/time:	Direction:	Weather:	Location code:
<b>3/5/2026 9:18 AM</b>	<b>U</b>	<b>1</b>	
Shape:	Material:	Height:	Width:
<b>C</b>	<b>PVC</b>	<b>18 in.</b>	

## Scores

Calculated at: **3/5/2026 9:20:43 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 17 Ashland, MA Main Street  
 Start date/time: Direction: Weather: Location code:  
 3/5/2026 9:27 AM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/5/2026 9:33:55 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
**18** **Ashland, MA** **Leland Avenue**  
 Start date/time: Direction: Weather: Location code:  
**3/5/2026 9:34 AM** **D** **1**  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: **3/5/2026 9:44:29 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
**3/5/2026 9:45 AM** **D** **Ashland, MA** **Leland Avenue**  
 Start date/time: Direction: Weather: Location code:  
**3/5/2026 9:45 AM** **D** **1**  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: **3/5/2026 9:50:27 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
**20** **Ashland, MA** **Leland Avenue Easement**  
 Start date/time: Direction: Weather: Location code:  
**3/5/2026 9:51 AM** **D** **1**  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: **3/5/2026 10:10:12 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	0	0000	0.0	0	0.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 21 Ashland, MA Leland Avenue Easement  
 Start date/time: Direction: Weather: Location code:  
 3/5/2026 10:10 AM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/5/2026 10:19:57 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 22 Ashland, MA Leland Avenue Easement  
 Start date/time: Direction: Weather: Location code:  
 3/5/2026 11:11 AM U 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/5/2026 11:14:57 AM

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
**23** **Ashland, MA** **Columbus Avenue**  
 Start date/time: Direction: Weather: Location code:  
**3/5/2026 11:40 AM** **U** **1**  
 Shape: Material: Height: Width:  
**C** **PVC** **18 in.**

## Scores

Calculated at: **3/5/2026 11:44:38 AM**

Grade	Structural:				O&M:				Overall:	
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0				0					
3	0				0					
4	0				0					
5	0				0					




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 Start date/time: Direction: Weather: Location code:  
 Shape: Material: Height: Width:  
**C PVC 18 in.**

## Scores

Calculated at: 3/5/2026 12:01:55 PM

Grade	Structural:			O&M:			Overall:			
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	1	1	1100	1.0	1	1.0
2	0									
3	0									
4	0									
5	0									




# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 25 Ashland, MA Brook Street  
 Start date/time: Direction: Weather: Location code:  
 3/5/2026 12:02 PM D 1  
 Shape: Material: Height: Width:  
 C PVC 18 in.

## Scores

Calculated at: 3/5/2026 12:06:35 PM

Grade	Structural:			O&M:			Overall:			
	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	7	4131	3.5	7	3.5
2	0									
3	0									
4	0									
5	0									



# Main Inspections Pipe Run and Scoring

Project name: Mainline ID: City: Street:  
 26 Ashland, MA Presidents Row  
 Start date/time: Direction: Weather: Location code:  
 3/5/2026 12:45 PM D 1  
 Shape: Material: Height: Width:  
 C PVC 15 in.

## Scores

Calculated at: 3/5/2026 12:50:15 PM

Grade	Segment Grade	Structural:			Segment Grade	O&M:			Overall:	
		Pipe Rating	Quick Rating	Pipe Rating Index		Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index
1	0	0	0000	0.0	0	4	4100	4.0	4	4.0
2	0				0					
3	0				0					
4	0				4					
5	0				0					

